

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080148-0

FROM

DATE REC'D 3-23-57
P.O. NO.

VENDOR PACKING SLIP NO.

PLANT #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.	
	DRAWING NO. AND DESCRIPTION										QUANTITY
3	322	0	9	0	22		03				
	Time Delay Assembly								3		
	IF #6471										

RECEIVED BY *J. Barcelos* INSPECTED BY *Dma* DATE 3/23/57 REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11578

RECEIVED FROM

PLANT #9

DATE REC'D 3-23-57
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.	
	DRAWING NO. AND DESCRIPTION										QUANTITY
2	322	0	9	0	20						
	Bracket Assembly with Adjust								2		
	IF #6471										
	Drawn on Stores App. #6471 for Plant #9										

RECEIVED BY *J. Barcelos* INSPECTED BY *Dma* DATE 3/23/57 REJECTS RETURNED ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080148-0